



THE KEY TO INVENTORIES SINCE 1994

CHECK IN INVENTORY OF
CONTENTS AND CONDITION
AT

SAMPLE ADDRESS
SAMPLE ADDRESS
SAMPLE ADDRESS

SAMPLE DATE
REF: SAMPLE

T: 01923 283 993 M: 07976 278450 info@oakwood-inventories.com www.oakwood-inventories.com

2 Orchard Drive, Chorleywood, Hertfordshire WD3 5QL V.A.T Reg No. 710 2888 49
Oakwood Inventories London Limited trading as Oakwood Inventories Registered in England and Wales Company Number: 8152483



Property
Redress



TABLE OF CONTENTS

GUIDANCE NOTES	1
ENTRANCE HALL & STAIRCASE.....	3
LANDING	7
BATHROOM.....	10
BEDROOM 1 - MASTER.....	16
INNER HALLWAY ONTO ENSUITE SHOWER ROOM.....	21
ENSUITE SHOWER ROOM.....	24
RECEPTION ROOM	29
BEDROOM 2.....	34
BEDROOM 3.....	40
KITCHEN.....	44
KEYS.....	55
METER READINGS	56
SMOKE ALARM AND CARBON MONOXIDE	57
SCHEDULE OF CONDITION.....	60
DECLARATION	61

GUIDANCE NOTES

INVENTORY DISCLAIMER

This is an independent inventory report that relates solely to the contents and condition of the property and does not form any part of a valuation or structural report.

All items and areas described within this report are recorded as observed at the time of inspection. Condition and cleanliness at check-out will be compared against the standard recorded at check-in.

Please note, we are not experts in antiques, furniture styles, fabrics, or materials. All descriptions are provided for identification purposes only, enabling comparison at the end of the tenancy.

For Health and Safety reasons we do not undertake to move heavy items of furniture nor access lofts, high level cupboards or any other inaccessible places. Inspection of flooring, wall surfaces and fixtures beneath, behind or above such items is therefore limited to what is visible and accessible at the time of inspection.

APPLIANCES AND SAFETY

Any electrical appliances tested, will be for power only and only where practicable. Boilers, gas fires, water supply, radiators, and security alarms are not tested. No assessment is made as to safety, suitability, certification, or compliance of any equipment is given only a record that the items exist within the property and the current condition. Industry regulations related to gas and electrical items as well as fire and safety for furnishings are the responsibility of the landlord. Any references made to certificates and/or labels are merely a record that they exist at the time of the inventory. The presence of any certificate, label, or documentation does not constitute verification of validity, compliance, or current status

Oakwood Inventories London Limited accept no responsibility for the functionality or performance of any smoke alarms and or carbon monoxide detectors listed. They may be tested only where practicable, any tests at the time of inventory inspection will have been so for audio purposes only as per manufacturer's instructions, but this does not mean in any way that they are still functioning or in full working effect after our checks. It is the tenant's responsibility to inspect/test any smoke alarms and carbon monoxide detectors within the property at regular intervals during the tenancy to ensure they are in working order as per manufacturer's instructions.

UTILITIES

It is the responsibility of the landlord and or agent to make us aware of the location of the utility meters. If a meter cannot be located or is inaccessible then a reading will not be taken and we will accept no responsibility. Any readings taken must be confirmed by the relevant utility companies as we cannot be held responsible for any discrepancies.

PHOTOGRAPHS

Photographs included within the report are provided for illustrative and reference purposes only and are intended to support the written descriptions of condition. They do not constitute a comprehensive or definitive record of the property, its fixtures, fittings, contents, or condition.

Not all items, areas, or aspects of condition are photographed. The written descriptions within the report remain the primary and authoritative record. Photographic appearance may be affected by lighting, angle, resolution, or other environmental factors and should not be relied upon independently.

CHECK OUT NOTES

At the end of the tenancy this inventory will be used for comparison purposes. All tenant possessions must be removed prior to the check out appointment and that all content should be returned to the same location as indicated in the check in inventory, any stored items should be unpacked and also returned to the same location. Additional charges may be incurred for unallocated time searching and or unpacking.

The property should be returned cleaned and in tidy condition to the same standard recorded at check-in especially floors, curtains, windows, upholstery appliances etc. We would suggest that you refer to your obligations within your tenancy agreement in this matter. Receipts for any professional cleaning should be provided at the check out.

Any reference to potential tenant responsibility for matters identified is provided for information only. Final decisions regarding liability rest solely with the landlord or managing agent and may be determined in accordance with the tenancy agreement, independent of our observations. We do not provide costings or assessments of financial liability.

SAMPLE

CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE [CLICK HERE](#)**

All items are assumed to be present and in good condition unless specifically noted otherwise in the check in condition column. The property was reported to have been professionally cleaned prior to check in and cleanliness is recorded as observed on the day of inspection only. Where no comment is recorded in the check in condition column, the item is deemed to be in an acceptable clean condition at the time of inspection.

ENTRANCE HALL & STAIRCASE		
DESCRIPTION	CHECK IN CONDITION	CHECK OUT CONDITION
DOOR		
Exterior: painted white with letter B in chrome, chrome spyhole, 2 chrome Banham locks	Grubby, few scuff marks to base exterior, few light scuff marks to centre, scuff to edge	
Interior painted white with 2 chrome Banham locks, chrome spyhole with cover, chrome arm door closer	Patchy around fittings, slight mid level scuff marks, handle loose on top lock	
WALLS		
Painted off-white	Newly painted, line scuff mark over coat rack, slightly patchy to mid level on staircase walls and scuff marks at top of stairs	
 24 Dec 2025 09:29		
WOODWORK		
Painted white with chrome and rubber doorstop to skirting	Good order, touched up area to skirting at entrance	




CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE [CLICK HERE](#)**

FLOORING		
Silver grey fitted carpet	Professionally cleaned, residual spot marks around entrance area, small paint mark left hand side of window, few spot marks and small paint mark by stairs up, flattened pile through walkway, slight shading to stair tread edges, few spot marks to staircase carpet, minor paint marks around edge of carpet	
		
		
CEILING		
Painted white	Area of small scuff marks by smoke alarm	
LIGHTING		
Circular pale grey ceiling light with opaque shade	In working order	

CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE** [CLICK HERE](#)

2 white plaster wall lights	In working order, slight shaded marks to left hand light	
WINDOWS		
2 sash windows, painted white, chrome window lock, 2 chrome pulls, 2 barrel locks to each window, 2 window lock keys, white painted sills	Cleaned to interior and exterior, slight paint marks to glass, few light scuff marks to sill area	
CURTAINS/BLINDS		
1 pale grey roller blind with metal pulley	Tested	
CONTENTS		
Wired smoke alarm to ceiling	Audio tested only	
Wooden coat rack to wall with 5 chrome hooks	Slight grubby marks	
White painted wooden handrail along staircase wall with 5 chrome brackets		
Double fitted cupboard, doors painted white, chrome knob handles	Fixture marks to walls, slightly dusty to interior	
• Metal Wylex fuse box with flap		
White double valve radiator with chrome and wooden valve		
Plastic light switch		
		

CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE [CLICK HERE](#)**




CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE** [CLICK HERE](#)

All items are assumed to be present and in good condition unless specifically noted otherwise in the check in condition column. The property was reported to have been professionally cleaned prior to check in and cleanliness is recorded as observed on the day of inspection only. Where no comment is recorded in the check in condition column, the item is deemed to be in an acceptable clean condition at the time of inspection.

LANDING		
DESCRIPTION	CHECK IN CONDITION	CHECK OUT CONDITION
DOOR		
N/A		
WALLS		
Painted off-white	Newly painted	
WOODWORK		
Painted white	Inner door frame onto bathroom has been undercoated only, slight grubby marks to mid levels to architraves	
FLOORING		
Continuation of silver grey fitted carpet	Professionally cleaned, slight rucking to centre, slightly loose to gripper onto bedroom 3 and bedroom 2, slight flattened pile through walkway, residual spot marks by bathroom area and at stairs, slight shading in front of kitchen, loose on gripper on to bedroom 2	
 		

CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE [CLICK HERE](#)**



CEILING

Painted white

LIGHTING

2 circular pale grey ceiling lights with opaque shades

WINDOWS

N/A


CURTAINS/BLINDS

N/A

CONTENTS

Paxton video entryphone	Tested for power only	
Heatmiser digital underfloor heating	Tested for power only	
Digital thermostat stuck to wall with Velcro pads	Tested for power only	
Access panel to ceiling		
2 wired smoke alarms to ceiling	Audio tested only	
Plastic light switches and plastic fuse points	2 fuse switches labelled Underfloor heating and towel rail	
Plastic isolator switch		

CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE [CLICK HERE](#)**




SAF

CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE** [CLICK HERE](#)

All items are assumed to be present and in good condition unless specifically noted otherwise in the check in condition column. The property was reported to have been professionally cleaned prior to check in and cleanliness is recorded as observed on the day of inspection only. Where no comment is recorded in the check in condition column, the item is deemed to be in an acceptable clean condition at the time of inspection.

BATHROOM		
DESCRIPTION	CHECK IN CONDITION	CHECK OUT CONDITION
DOOR		
Painted white with chrome lever handles and chrome twist lock, brush door strip around inner frame	Very minor chip defect to top interior, interior handle very slightly loose	
WALL		
Grey porcelain tiles with chrome trim	Mildew to sealant by window, few minor paint marks high level by windows	
 24 Dec 2025 09:32		
WOODWORK		
Architrave painted white	Very patchy	



CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE [CLICK HERE](#)**



FLOORING

Darker grey porcelain tiles with chrome and rubber doorstop and chrome door strip

Professionally cleaned, scattered dull marking, slight scale residue by wash basin



CEILING

Painted white

LIGHTING


3 inset LED spotlights

In working order

CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE** [CLICK HERE](#)

WINDOWS		
White painted sash window, 2 chrome pulls, 2 chrome barrel locks	Cleaned to interior only, slight cracking by housing for left hand barrel locks, privacy film added to bottom panes, pink staining to privacy film, flaking to paintwork around base of frame, barrel locks found in kitchen, base of frame not fully cleaned and discolouration	
Secondary glazing		
		
		
CURTAINS/BLINDS		
N/A		
CONTENTS		
Polished chrome ladder heated towel rail with thermostat	Clean	
White Bette bath with chrome pop-up waste, combined chrome bath and shower mixer, fitted chrome shower with chrome shower hose, multi function chrome coloured shower head, chrome shower holder	No plug seen	

CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE [CLICK HERE](#)**



2-section chrome framed tempered glass shower screen with rubber seals	Professionally cleaned, unable to clean to inaccessible area where it joins the wall, minor discolouration to seal	
Bath panel tiled as per walls		
Advent extractor	In working order	
Recessed cabinet with double white doors with chrome handles, 2 shelves to interior	Professionally cleaned, areas of staining to back panel, slight blistering to base of doors	




White WC with white seat and lid with soft closer, encased cistern with chrome dual flush	Professionally cleaned, slight discolouration to underside of seat	
Chrome toilet roll holder		
Plastic shaver point		
Inset rectangular bevelled mirror to wall		

CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE** [CLICK HERE](#)

White wash basin with chrome Grohe mixer tap and chrome spring waste	Professionally cleaned	
White gloss laminate vanity unit with 2 drawers		
Spare chrome shower rail	Not fitted	
		
		
		
		

CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE [CLICK HERE](#)**




CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE** [CLICK HERE](#)

All items are assumed to be present and in good condition unless specifically noted otherwise in the check in condition column. The property was reported to have been professionally cleaned prior to check in and cleanliness is recorded as observed on the day of inspection only. Where no comment is recorded in the check in condition column, the item is deemed to be in an acceptable clean condition at the time of inspection.

BEDROOM 1 - MASTER		
DESCRIPTION	CHECK IN CONDITION	CHECK OUT CONDITION
DOOR		
Painted white with chrome lever handles, lock with 3 keys, twist lock to interior, brush door strip around inner frame		
 <div style="text-align: right; font-size: small;">24 Dec 2025 09:12</div>		
WALLS		
Painted off-white	Newly painted, line scuff mark over headboard	
 <div style="text-align: right; font-size: small;">24 Dec 2025 09:36</div>		

CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE [CLICK HERE](#)**

WOODWORK		
Painted white with chrome and rubber doorstop to skirting	Newly painted, inner door frame onto inner hallway to bathroom is undercoated only	
FLOORING		
Continuation of fitted carpet, chrome door strips	Professionally cleaned, not inspected under furniture, faint spot marks at foot of bed	
		
CEILING		
Painted white		
LIGHTING		
Pendant fitting with grey herringbone shade	In working order	
WINDOWS		
White framed sash window with 2 chrome pulls	Cleaned to interior, slight mildew around edges of upper frame	

CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE [CLICK HERE](#)**



CURTAINS/BLINDS

Grey vinyl blackout roller blind with metal pulley	Tested	
Grey mesh roller blind with metal pulley	Tested	

CONTENTS


White double valve radiator with chrome and wooden valve		
Wired smoke alarm to ceiling	Audio tested only	
Ikea white double fitted wardrobe with white laminate doors with chrome handles:		
<ul style="list-style-type: none"> White laminate interior 2 shelves 2 drawers White hanging rail 		
Access panel to ceiling		
Grey suede style 2 section double divan with chrome coloured legs		
Dark grey suede style upholstered headboard		
Off white Tendersleep Delight Ortho double mattress	Minor spot mark to underside, inspected both sides	

CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE [CLICK HERE](#)**





Plastic dimmer switches and plastic power points

Plastic telephone point



CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE** [CLICK HERE](#)



SAF

CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE** [CLICK HERE](#)


All items are assumed to be present and in good condition unless specifically noted otherwise in the check in condition column. The property was reported to have been professionally cleaned prior to check in and cleanliness is recorded as observed on the day of inspection only. Where no comment is recorded in the check in condition column, the item is deemed to be in an acceptable clean condition at the time of inspection.

INNER HALLWAY ONTO ENSUITE SHOWER ROOM		
DESCRIPTION	CHECK IN CONDITION	CHECK OUT CONDITION
DOOR		
Painted white, chrome lever handles	Scuff mark over handle to exterior, touched up area to edge of door by lock	
WALLS		
Painted white	Newly painted	
WOODWORK		
Painted white		
FLOORING		
Continuation of silver grey fitted carpet, chrome door strips	Professionally cleaned, flattened pile, slightly lifting at door strip onto shower room causing frays along edge,	
 		
CEILING		
Painted white		

CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE [CLICK HERE](#)**

LIGHTING		
Inset LED spotlight	In working order	
WINDOWS		
N/A		
CURTAINS/BLINDS		
N/A		
CONTENTS		
White double valve radiator with chrome and wooden valve		
Heatmiser underfloor heating control	Tested for power only	
Double Ikea fitted wardrobe, white laminate doors with chrome handles:	Light shading to door edge	
<ul style="list-style-type: none"> White laminate interior Shelf Drawer Hanging rail 		
Plastic light switch		
Plastic dimmer switch		
Plastic power points	Power point left side of entrance is loose	
Plastic isolator switch		
Plastic fuse point	Towel rail written to front	

CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE** [CLICK HERE](#)




CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE** [CLICK HERE](#)

All items are assumed to be present and in good condition unless specifically noted otherwise in the check in condition column. The property was reported to have been professionally cleaned prior to check in and cleanliness is recorded as observed on the day of inspection only. Where no comment is recorded in the check in condition column, the item is deemed to be in an acceptable clean condition at the time of inspection.


ENSUITE SHOWER ROOM		
DESCRIPTION	CHECK IN CONDITION	CHECK OUT CONDITION
DOOR		
Sliding door, painted white, recessed chrome handles	Light finger marking to edge on interior	
WALLS		
Grey porcelain tiles with chrome trim	Professionally cleaned, minor scale mark under WC	
WOODWORK		
Architrave painted white		
FLOORING		
Darker grey porcelain tiles with chrome and rubber doorstop and chrome door strip	Professionally cleaned	
CEILING		
Painted white		
LIGHTING		
2 inset LED spotlights with chrome trim	In working order	
WINDOWS		
Sash window painted white with opaque glazed panes, 2 chrome pulls, housing for barrel locks (no barrel locks fitted)	Cleaned to interior, mildew around frame, 2 chip defects to frame right hand side	

CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE [CLICK HERE](#)**



White framed sliding secondary glazing		
CURTAINS/BLINDS		
N/A		
CONTENTS		
Polished chrome ladder heated towel rail with thermostat	Screws requires tightening to top brackets as comes away	
Recessed medicine cabinet with mirrored door, white laminate interior, 2 shelves		
Plastic shaver point		
White wash basin with chrome Grohe mixer tap and chrome spring waste	Professionally cleaned	
White gloss laminate vanity unit with 2 drawers, chrome toilet roll holder attached to side	Professionally cleaned	
Chrome ladder heated towel rail		
White WC with white seat and lid with soft closer, encased cistern with chrome dual flush	Professionally cleaned but light scale residue to pan	

CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE [CLICK HERE](#)**






Chrome toilet roll holder		
Manrose extractor to wall	In working order	
Shower cubicle with tempered glass sliding door with chrome handle, magnetic rubber seals, fixed tempered glass side panel	Professionally cleaned, minor light scale residue around base of frame	



<ul style="list-style-type: none"> Large white shower tray with chrome coloured waste 		
<ul style="list-style-type: none"> Fitted chrome shower mixer controls 	Top tap head slightly loose	
<ul style="list-style-type: none"> Chrome hand shower with chrome shower hose and cylindrical chrome shower head on chrome shower holder 		
<ul style="list-style-type: none"> Circular overhead chrome shower head 		

CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE [CLICK HERE](#)**



CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE** [CLICK HERE](#)



SAMPLE

CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE** [CLICK HERE](#)


All items are assumed to be present and in good condition unless specifically noted otherwise in the check in condition column. The property was reported to have been professionally cleaned prior to check in and cleanliness is recorded as observed on the day of inspection only. Where no comment is recorded in the check in condition column, the item is deemed to be in an acceptable clean condition at the time of inspection.

RECEPTION ROOM		
DESCRIPTION	CHECK IN CONDITION	CHECK OUT CONDITION
DOOR		
Painted white with chrome lever handles, twist lock to interior, brush door strip around inner frame	Low level scuff mark to exterior	
WALLS		
Painted off-white	Newly painted	
WOODWORK		
Painted white, chrome and rubber doorstop to skirting	Odd scuffs to skirting	
FLOORING		
Continuation of oak wood strip flooring with chrome door strip	Professionally cleaned, good order, not inspected under furniture, few scuff marks forward of entrance	
 		
CEILING		
Painted off white with ceiling rose painted off white		

CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE [CLICK HERE](#)**

LIGHTING		
Pendant fitting with large pleated white vinyl shade	In working order, minor dust to shade	
3 half-moon plaster wall lights painted as per walls	In working order	
WINDOWS		
White framed double glazed casement window, 2 fixed side window	Cleaned to interior only, handle slightly loose to right hand window, slight shrinkage cracking around outer frame	
CURTAINS/BLINDS		
2 grey vinyl roller blinds with metal pulleys	Tested	
CONTENTS		
White double valve radiator with chrome and wooden valve		
Grey 3 seater Click n Clack sofa bed with fixed seat cushions and black wooden legs	Mechanism tested, professionally cleaned	
Further 2 seater grey upholstered sofa with pleated back rest and fixed cushions, black legs	Professionally cleaned	
Rectangular tempered glass coffee table with chrome frame	Cleaned	
Matching rectangular lamp table	Cleaned	
Rectangular tempered glass dining table with chrome frame	Cleaned, slightly smearable to glass	
6 black plastic dining chairs with black leather style padded seats, black metal frames	Cleaned, light rub marks to back rests on each	

CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE [CLICK HERE](#)**




Plastic dimmer switch and plastic power points, 1 power point with USB chargers




Plastic telephone point

Wired smoke alarm to ceiling

Audio tested only



CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE** [CLICK HERE](#)




CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE** [CLICK HERE](#)



SAMPLE

CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE** [CLICK HERE](#)

All items are assumed to be present and in good condition unless specifically noted otherwise in the check in condition column. The property was reported to have been professionally cleaned prior to check in and cleanliness is recorded as observed on the day of inspection only. Where no comment is recorded in the check in condition column, the item is deemed to be in an acceptable clean condition at the time of inspection.

BEDROOM 2		
DESCRIPTION	CHECK IN CONDITION	CHECK OUT CONDITION
DOOR		
Painted white with chrome lever handles, lock with 3 keys, twist lock to interior, brush door strip around inner frame	Minor shading to edge on interior	
 24 Dec 2025 09:16		
WALLS		
Painted off-white	Newly painted, high level leak stain left hand side of window	
 24 Dec 2025 09:47		

CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE [CLICK HERE](#)**

WOODWORK		
Painted white with chrome and rubber doorstop to skirting	Shrinkage cracking in parts	
FLOORING		
Silver grey fitted carpet with chrome door strip	Professionally cleaned, not inspected under furniture, residual spot marks at foot of bed and by radiator, foam stuck in carpet around right hand radiator pipe	
 		
		
CEILING		
Painted white		
LIGHTING		
Pendant fitting with grey herringbone shade	In working order	

CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE** [CLICK HERE](#)

WINDOWS		
3 white framed sash windows, 2 chrome pulls to centre window, chrome window lock, 1 chrome pull to both side windows	Cleaned to interior only, painted over cable to left hand side	
CURTAINS/BLINDS		
3 grey vinyl blackout roller blinds with metal pulleys	tested	
3 grey mesh roller blinds with metal pulleys	Tested	
CONTENTS		
White double valve radiator with wooden and chrome valve		
Double Ikea fitted wardrobe left hand side of entrance, white laminate doors, 2 chrome handles	Very minor shading to door edges, top drawer front slightly loose	
<ul style="list-style-type: none"> White laminate interior Shelf Drawer Hanging rail 		
Fitted shelving to right side of wardrobe, painted white		
Double Ikea fitted wardrobe left hand side of bed area, white laminate doors, 2 chrome handles	Good order	
<ul style="list-style-type: none"> White laminate interior Shelf Drawer Hanging rail 		
Fitted shelving left side of wardrobe, painted white	Light usage wear and tear shading	
Grey suede style 2 section double divan with chrome coloured legs		
Dark grey suede style upholstered headboard	Very patchy shaded appearance	



CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE [CLICK HERE](#)**



Off white Tendersleep Delight Ortho double mattress	Good order, minor light shading to top, inspected both sides	remains in overall good order, minor light shading to top
Wired smoke alarm to ceiling	Audio tested only	
Plastic light switch		
Plastic power points		



CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE [CLICK HERE](#)**



CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE** [CLICK HERE](#)



SAMPLE

CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE** [CLICK HERE](#)



All items are assumed to be present and in good condition unless specifically noted otherwise in the check in condition column. The property was reported to have been professionally cleaned prior to check in and cleanliness is recorded as observed on the day of inspection only. Where no comment is recorded in the check in condition column, the item is deemed to be in an acceptable clean condition at the time of inspection.

BEDROOM 3		
DESCRIPTION	CHECK IN CONDITION	CHECK OUT CONDITION
DOOR		
Painted white with chrome lever handles, lock with 3 keys, twist lock to interior, brush door strip around inner frame	Low level scuff mark to interior of door	
		
WALLS		
Painted off-white	Newly painted	
WOODWORK		
Painted white with chrome and rubber doorstop to skirting	Wear and tear shrinkage cracking to skirting, few low level scuff marks to architrave	
FLOORING		
Silver grey fitted carpet with chrome door strip	Professionally cleaned	
CEILING		
Painted white		
LIGHTING		
Pendant fitting with grey shade	In working order	

CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE [CLICK HERE](#)**

WINDOWS		
White framed double glazed sash window with 2 chrome pulls and 2 chrome window locks	Cleaned to interior	
CURTAINS/BLINDS		
2 grey vinyl blackout roller blinds with metal pulleys and plastic pulls	Tested	
2 grey mesh roller blinds with metal pulleys	Tested	
CONTENTS		
White double valve radiator with wooden and chrome valve		
Wired smoke alarm to ceiling	Audio tested only	
Free standing grey gloss laminate double wardrobe:	Area of scratch marking to base interior right hand side, good order	
<ul style="list-style-type: none"> Shelf Hanging rail 		
Grey gloss chest of 4 drawers		
Grey suede style 2 section double divan with chrome coloured legs		
Dark grey suede style upholstered headboard	Patchy faded area to left hand side	
		
Off white Tendersleep Delight Ortho double mattress		
Plastic dimmer switch and plastic power points		
Plastic telephone point		

CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE [CLICK HERE](#)**





CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE** [CLICK HERE](#)



SAMPLE

CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE** [CLICK HERE](#)

All items are assumed to be present and in good condition unless specifically noted otherwise in the check in condition column. The property was reported to have been professionally cleaned prior to check in and cleanliness is recorded as observed on the day of inspection only. Where no comment is recorded in the check in condition column, the item is deemed to be in an acceptable clean condition at the time of inspection.

KITCHEN		
DESCRIPTION	CHECK IN CONDITION	CHECK OUT CONDITION
DOOR		
Painted white, chrome lever handles	Scuff marking low level on exterior, touch up mark to base exterior	
WALLS		
Painted off-white	Newly painted	
Narrow grey speckled pattern porcelain tiles with chrome edging	Professionally cleaned	
WOODWORK		
Painted white, chrome and rubber doorstop to skirting		
FLOORING		
Oak wood strip flooring	Professionally cleaned, few scuff marks around breakfast bar area, areas of faded staining left side of refrigerator area, small white stains to same area, dark line mark right hand side of fridge, areas of discolouration left hand side of fridge area possibly part of design of the flooring to this area	
 		

CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE [CLICK HERE](#)**



Matching steps leading down to lower kitchen area,
plastic capping to edge of 2 of the steps

CEILING

Painted white

LIGHTING

7 inset LED spotlights

In working order

WINDOWS

3 sash windows painted white with 2 chrome pulls, 2
chrome window locks, sills painted white


Cleaned to interior

CURTAINS/BLINDS

3 grey vinyl roller blinds with metal pulleys

Tested

CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE [CLICK HERE](#)**

CONTENTS		
White double valve radiator with wooden and chrome valve		
Wired heat/smoke detector to ceiling	Audio tested only	
Further wired smoke detector to ceiling	Audio tested only	
Range of grey gloss laminate wall, base and drawer units with recessed handles	2 chip defects to interior base of cupboard under sink, 2 shelf supports not seen for shelves to far left cupboard	
		
		
<ul style="list-style-type: none"> • Fitted large grey plastic cutlery tray • Grey gloss laminate kickspaces 		
Shades of silver grey granite worksurfaces with drainer grooves along sink wall	Professionally cleaned	
Matching work surface right hand side of refrigerator		
Matching breakfast bar with chrome leg	Scuffs to right leg	
3 dark grey suede style upholstered breakfast bar stools with black metal frames and foot rests	Spot marks	

CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE [CLICK HERE](#)**



Inset 1 1/2 bowl stainless steel sink unit with surface mounted chrome mixer taps and 2 strainer plugs

Requires light further clean, spout to tap very slightly loose



Worcester boiler

Tested for power only

CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE** [CLICK HERE](#)

Free standing Carbon Monoxide detector	Battery requires replacing – this has been reported	
Integral AEG 7000 Series washer/dryer, model L7WE7631BI, serial no. 13300174	Professionally cleaned, tested for power only, manufacturer's sticker to casing	
Integral Bosch dishwasher with 2 baskets and cutlery drawer, model SL6PW1B, serial no. 402030527503002340	Professionally cleaned, tested for power only	
Bosch 4-ring black induction hob with digital controls, model PIE631BB5, serial no. 9001601785	Professionally cleaned, tested for power only, burnt on residues to rings	
	 	
Stainless steel Lamona extractor hood with digital controls, glass panel to front, 2 filters, 2 lights, model no: LAM2877, serial no: 221700568	Slightly greasy, requires further cleaning, tested for power only	
		


CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE [CLICK HERE](#)**

Fitted stainless steel trim Bosch oven with black glass door front with brushed stainless steel handle, 1 full width grill tray, 2 half width grill trays, 2 racks, model HR5B20F0, serial no. 492060505737019830	Professionally cleaned, tested for power only	
Integral Bosch refrigerator/freezer with salad tray, 4 glass shelves, 3 door compartments, 3 freezer compartments, light fitting, egg tray, ice cube tray, model KGKIUU29A, serial no. 25112052748755501	Professionally cleaned, tested for power only, 1 door compartment badly cracked	
		
Large quantity of barrel locks and key seen to cupboard		
Energy meter		
Remote sensor		
Wall mounted fire blanket		
Wall mounted fire extinguisher		
Assorted instruction manuals		
Plastic dimmer switch		
Plastic power points and fuse points		
Power point with USB chargers		
Remote thermostat		


CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE [CLICK HERE](#)**



CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE** [CLICK HERE](#)



CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE** [CLICK HERE](#)



CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE** [CLICK HERE](#)



CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE [CLICK HERE](#)**



SAMPLE

CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE** [CLICK HERE](#)

KEYS

DESCRIPTION

3 sets of 2 keys comprising 1 Yale key and 1 Banham key no. 471460 and 1 meter cupboard key collected and returned to sample agent,



SAMPLE

CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE** [CLICK HERE](#)

METER READINGS

ELECTRIC METER:		GAS METER:	
READING	04943 kwh	READING	01867.473
SERIAL NUMBER	22J0321191	SERIAL NUMBER	23142388
LOCATION	Communal hall cupboard	LOCATION	Communal hall cupboard
			
WATER METER:		n/a	

CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE [CLICK HERE](#)**

SMOKE ALARM AND CARBON MONOXIDE

SMOKE ALARM		CARBON MONOXIDE	
LOCATION	TESTED	LOCATION	TESTED
Entrance hall, landing x 2, reception room, bedroom 1, 2 and 3	Audio tested	Kitchen	Battery not working and reported to agent
	24 Dec 2025 09:09		24 Dec 2025 09:25
			
24 Dec 2025 09:10			

CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE [CLICK HERE](#)**



CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE** [CLICK HERE](#)



SAMPLE

CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE** [CLICK HERE](#)

SCHEDULE OF CONDITION

	CHECK IN CONDITION	CHECK OUT CONDITION
GENERAL CONDITION/CLEANING	Professionally cleaned	
DECORATIVE CONDITION	Newly painted where noted, defects as noted	
FLOORING	Professionally cleaned, defects as noted	
WINDOWS	Cleaned to interior only	
CURTAINS/BLINDS	Good order, tested	
UPHOLSTERY	Sofas professionally cleaned, spot marks to bar stools as noted	
LINEN	n/a	
KITCHEN APPLIANCES	Professionally cleaned, tested for power only, defects as noted	
LIGHTING	In working order	
GARDEN/BALCONY	n/a	

CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE [CLICK HERE](#)**

DECLARATION

This inventory has been examined and, subject to marginal comments, found to be correct

ON BEHALF OF THE LANDLORD	PRINT	
	SIGN	
	DATE	

ON BEHALF OF THE TENANT	PRINT	
	SIGN	
	DATE	

CTRL + SCROLL TO ENLARGE SCREEN IMAGE OR PINCH ON MOBILE. **FULL GALLERY ONLINE [CLICK HERE](#)**